Annexure D

BUILDING SAFETY CERTIFICATE

No.: 1041/ HBC/2025-26

Dated: 1105 2025

Certified that the existing building St. Joseph's School(name of the building or premises) atNichlaul, Dist.- Maharajganj (U.P.) (Address) is having block(s)/Floor(s) as per details below:

f Floor(s) in G1+5					
1000	2	5.	5.	5.	5.

The building is owned/occupied bySt. Joseph's School(name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of PWD Maharajganj (Name of Department/ Govt.) on 29.04.2625 (Date of inspection) in the presence of Reji A.C., S/o A.C. Chandy, R/o Mo.- Harredih, Tehsil- Nichlaul, Dist.- Maharajganj (U.P.) (Name and addresses of the Manager) and that the building/premises is fit for occupancy for running school with effect from on occupancy for a period of syears in accordance with rule and subject to compliance of the specific conditions as appended.

1

2

3.

4

Issued on ot-05-3025 at Maharajganj by PWD Maharajganj.

सहायक अभियन्ता प्राट खंव, लोठ निठ बिट 報言ではまる

Signature with Seal:

Designation:

Name & Address of Department/ Office

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for details

> Principal St. Joseph's School Michiaul, Dist-Maharajgani 273304-(U.P.)

Manager St. Joseph's School Nichlaul, Dist-Maharajganj 273304-(U.P.)